

Coded Note Number: HC031

Revision: C001

Date: April 26, 2019

Title: HC031 - VALVE WELDING HEAT CONTROL

This seawater service valve shall be disassembled prior to welding to avoid damage to the valve internals. Valve internals shall be lubricated with A-A-50433 grease prior to reassembly (refer to CCPP-8005 & M42-18.3 for guidance).

Revision History Table		
Rev	Description	Revision Date
C001	Original Issue	04-26-19

This revision history is provided for convenience and does not alleviate the supplier's responsibility with understanding and complying with the full coded note.