

Coded Note Number: **T1800**
Revision: **C002**
Date: **June 21, 2017**
Title: **VALVE PACKING RESTRICTIONS**

This revision history is provided for convenience and does not alleviate the supplier's responsibility with understanding and complying with the full coded note. Change from Revision C001– Editorial change for clarification. Bolded font indicates changed/added content. [Text deleted] inserted in the document indicates the removal of content.

Graphitic yarn packing per MIL-P-24583 **[Text deleted]** Class 2 **[Text deleted]** shall be manufactured by one of the following vendors:

- a. AW Chesterton Company
- b. Garlock
- c. American Braiding

For valves with MIL-P-24583 **Class 2** packing installed, all packing shall be removed and replaced if any of the following conditions occur before shipment:

- a. Adhesion of material to the valve stem with a visible thickness which can flake off.
- b. Evidence of packing particulate in valve internals. (Reestablishing valve cleanliness is required)
- c. Excessive torque required to operate the valve.