

If the valve is installed during welding, Weld Technique Number (WTN) as normal and mid-position valve. If the valve is installed during welding and mid-positioning is not possible, disassemble prior to welding. Swing check and lift check valves can be mid-positioned by turning the valve upside down prior to welding.