

Follow preheat and interpass instructions of the applicable Weld Technique Number (WTN). Mid- position the stem / disc. Follow Section G (Reduced Heat Input / Cooling Methods) of W91 / 191 Appendix A.