

Weld in quarters using 125 F interpass temperature. Follow the recommendations provided in Section D and Section G (Reduced Heat Input / Cooling Methods) of W91 / 191 Appendix A.