

Coded Note Number: **T1800**

Revision: **C001**

Date: **May 3, 2017**

Title: **VALVE PACKING RESTRICTIONS**

Graphitic yarn packing per MIL-P-24583 shall be Class 2 and shall be manufactured by one of the following vendors:

- a. AW Chesterton Company
- b. Garlock
- c. American Braiding

For valves with MIL-P-24583 packing installed, all packing shall be removed and replaced if any of the following conditions occur before shipment:

- a. Adhesion of material to the valve stem with a visible thickness which can flake off.
- b. Evidence of packing particulate in valve internals. (Reestablishing valve cleanliness is required)
- c. Excessive torque required to operate the valve.