

Coded Note Number: T1800
Revision: C003
Date: February 2, 2022
Title: VALVE PACKING RESTRICTIONS

1. Graphitic yarn packing per MIL-P-24583 Class 2 shall be manufactured by one of the following vendors:
 - a. AW Chesterton Company
 - b. Garlock
 - c. American Braiding
2. For valves with MIL-P-24583 Class 2 packing installed, all packing shall be removed and replaced if any of the following conditions occur before shipment:
 - a. Adhesion of material to the valve stem with a visible thickness which can flake off.
 - b. Evidence of packing particulate in valve internals. (Reestablishing valve cleanliness is required)
 - c. Excessive torque required to operate the valve.
3. If a packing set is ordered consisting of packing manufactured in accordance with Mil-P-24503 and Mil-P-24583, then this coded note is applicable only to the packing manufactured in accordance with Mil-P-24583.

Revision History Table		
Rev	Description	Revision Date
C003	Added- If a packing set is ordered consisting of packing manufactured in accordance with Mil-P-24503 and Mil-P-24583, then this coded note is applicable only to the packing manufactured in accordance with Mil-P-24583.	2-2-2022
C002	Editorial change for clarification.	6-2-2017

This revision history is provided for convenience and does not alleviate the supplier's responsibility with understanding and complying with the full coded note.