

Coded Note Number: **W1370**

Revision: **C001**

Date: **August 22, 2018**

Title: **FITTINGS MACHINED FROM PLATE PROHIBITION; WELD REPAIR RESTRICTIONS**

1. Fittings shall not be machined directly from plate.
  
2. Weld Repair Restrictions
  - 2.1 Base metal weld repair is strictly prohibited without a Vendor Information Request (VIR) approval from Newport News Shipbuilding (NNS) for each specific repair. Once authorized, repair shall be performed in accordance with an NNS approved weld repair procedure.
  
  - 2.2 Weld repair of in-process fabrication welds shall be performed in accordance with the NNS approved weld procedure.

Revision History Table		
Rev	Description	Revision Date
C001	Initial Issue	8/22/2018