

TEST REPORTS FOR PERFORMANCE OF  
NONDESTRUCTIVE TESTS (ULTRASONIC TESTING)

TEST REPORTS SHOWING THE RESULTS OF ULTRASONIC TESTING (UT) IS  
REQUIRED. SELLER SHALL RECORD:

- A. THE NDT METHOD/S USED.
- B. DESCRIPTION OR UNIQUE IDENTIFICATION OF THE ITEM INSPECTED.
- C. PROCEDURE IDENTIFICATION.
- D. THE PERFORMING ACTIVITY, WHETHER IT BE THE SELLER, A SUB-TIER  
SUPPLIER OR A TEST LAB.
- E. QUANTITY INSPECTED.
- F. ACCEPTANCE STANDARD USED.
- G. QUANTITY ACCEPTED/REJECTED.
- H. DATE OF INITIAL INSPECTION AND INSPECTOR IDENTIFICATION.
- I. INSTRUMENT MANUFACTURER, MODEL NUMBER, AND SERIAL NUMBER OF  
UNIT.
- J. TRANSDUCER SIZE AND TYPE, SEARCH BEAM ANGLE, AND TEST  
FREQUENCY.
- K. COUPLANT USED.
- L. CALIBRATION STANDARD NUMBER.
- M. SIGNATURE OF THE INSPECTOR.

2. IN ADDITION, THE SELLER SHALL ATTACH A COPY OF THE BUYERS VPAR  
THAT APPROVED THE PROCEDURE TO THE TEST REPORT.

3. TEST REPORTS AND/OR OTHER VERIFICATION OF CONFORMANCE  
DOCUMENTS SHALL BE SIGNED AND DATED BY THE SELLER'S AUTHORIZED  
REPRESENTATIVE.

EVIDENCE OF ALL TESTS AND INSPECTIONS PERFORMED AS REQUIRED BY  
THE SPECIFICATION MUST BE MAINTAINED BY THE SELLER; HOWEVER,  
RECORDS FOR ONLY THOSE TESTS REQUESTED ABOVE SHALL BE  
FORWARDED WITH THE SHIPMENT.

TEST REPORTS SHALL BE ATTACHED TO THE PACKING LIST. WHERE  
MORE THAN ONE CONTAINER OR PACKAGE IS INCLUDED IN THE SHIPMENT,  
THE TEST REPORTS SHALL BE ATTACHED SECURELY TO OR PLACED IN ONE  
CONTAINER OR PACKAGE AND CLEARLY IDENTIFIED ON THE OUTSIDE.