

1 COPY- WHEN VISUAL INSPECTION IS REQUIRED FOR CASTINGS IAW S9074-AR-GIB-010/278 (VT), TEST REPORTS SHOWING THE RESULTS OF VISUAL INSPECTION IS REQUIRED. SELLER SHALL RECORD:

- A. THE NDT METHOD/S USED.
- B. DESCRIPTION OR UNIQUE IDENTIFICATION OF THE ITEM INSPECTED.
- C. PROCEDURE IDENTIFICATION.
- D. THE PERFORMING ACTIVITY, WHETHER IT BE THE SELLER, A SUB-TIER SUPPLIER OR A TEST LAB.
- E. QUANTITY INSPECTED.
- F. ACCEPTANCE STANDARD USED.
- G. QUANTITY ACCEPTED/REJECTED.
- H. DATE OF INITIAL INSPECTION AND INSPECTOR IDENTIFICATION.

2. SUBMITTAL OF VISUAL WORKMANSHIP PROCEDURES IN ACCORDANCE WITH STANDARD CLAUSE 60-67 IS NOT REQUIRED.

3. TEST REPORTS AND/OR OTHER VERIFICATION OF CONFORMANCE DOCUMENTS SHALL BE SIGNED AND DATED BY THE SELLER'S AUTHORIZED REPRESENTATIVE.

EVIDENCE OF ALL TESTS AND INSPECTIONS PERFORMED AS REQUIRED BY THE SPECIFICATION MUST BE MAINTAINED BY THE SELLER; HOWEVER, RECORDS FOR ONLY THOSE TESTS REQUESTED ABOVE SHALL BE FORWARDED WITH THE SHIPMENT.

TEST REPORTS SHALL BE ATTACHED TO THE PACKING LIST. WHERE MORE THAN ONE CONTAINER OR PACKAGE IS INCLUDED IN THE SHIPMENT, THE TEST REPORTS SHALL BE ATTACHED SECURELY TO OR PLACED IN ONE CONTAINER OR PACKAGE AND CLEARLY IDENTIFIED ON THE OUTSIDE.