

Follow preheat and interpass instructions of the applicable Weld Technique Number (WTN). Mid-position valve if possible. Follow Section G (Reduced Heat Input / Cooling Methods) of W91 / 191 Appendix A.