

IC197
Revision Level C005
Revision Date September 27, 2011
TAGGING OF HOSE FOR SAFE HANDLING

TAGGING OF HOSE/HOSE ASSEMBLIES FOR SAFE HANDLING INSTRUCTIONS

- A. EACH END OF THE HOSE/HOSE ASSEMBLIES SHALL HAVE A METAL TAG ATTACHED. THE TAG MUST BE METAL, WITH DIE STAMPED (ROUND BOTTOM) 1/8 INCH (MINIMUM) HIGH CHARACTERS IN ACCORDANCE WITH MIL-STD-792 TYPE V, ATTACHED WITH A WIRE OR NYLON TY-WRAP IN SUCH A WAY AS TO NOT INTERFERE WITH END CONNECTION CONTAINMENTS AND CONTAIN THE FOLLOWING INFORMATION:

SPECIAL HANDLING INSTRUCTIONS FOR HOSE

1. DO NOT EXCEED MINIMUM BEND RADIUS OF *_*.
2. DO NOT TWIST OR TORQUE. DO NOT BEND HOSE AT END FITTINGS.
3. COILED HOSES MUST BE UPRIGHTED AND UNROLLED THROUGH ITS FULL LENGTH.
4. DATE OF MANUFACTURE *_*.
5. VENDOR HYDRO TEST PRESSURE *_* PSI & DATE *_*.
6. MAXIMUM WORKING PRESSURE *_* PSI.

* SUPPLIER SHALL INSERT APPLICABLE INFORMATION.