

Coded Note Number: **LI018**
Revision: **C001**
Date: **January 28, 2013**
Title: **Calibration Results**

For Test instruments 100 PSI and greater; select the points at or nearest to the cardinal point at 10% intervals for 10% to 100% of full scale.

If the Test instrument is less than 100 PSI; select 5 or 6 test points that are at or nearest to the cardinal points.

Record the values selected above in an increasing order for the pressure gauge measurements.

Record the values listed in the preceding steps, except for the highest value, in a decreasing order for the decreasing pressure measurements.

Supplier is to record the data obtained above and provide 2 copies of the calibration results with the material.